




Clifton Phillips, PE.
Lead Gas System Integrity Engineer
Memphis Light, Gas and Water

CONTEXT


- MLGW
 - Service Territory Shelby County, TN
 - Largest 3 service municipal utility
 - Gas in service for over 100 yrs
 - Gas Distribution Main 4,846 Miles
 - Gas Services 307,967
 - ~5,000 Records associated per year

THE ISSUE

- Most services are not in GIS
 - Not accurate for reporting/risk analysis
 - No electronic data on services
 - Material
 - Size
 - Number




- Crews do not have access to records
 - Locating
 - Leak Survey
 - Construction
 - Corrosion



APPROACH

- 2 Pronged Multi Year Process
 - Partner with University of Memphis to map services
 - Use best available historical records
 - Partner with Leak Survey to collect GPS coordinates at risers



MAPPING

- Map Services
 - Do you include all historical info?
 - Multiple GSR's for most services
 - What actual attribute info do you collect?
 - Do you collect fitting info?
 - Valves
 - Couplings
 - Linear Referencing

f,	MAINTEN	- 区 CO 区 M - 区 M	ANCE OF GAS SERVICE Z CITY S SERVINTOWN 1995			
_	Comparison Com	Li weld Ownerte Add				
	Montre offe -da w		REMORES CLINES MEMBERS CLINES REMORED SUPPLIES CLINES REMORED WITH TO CLINE REMORED WITH THE STORY LINE REMORED TO SERVICE REMORED RISER ONLY CLINES SERVICE STUR SERVICE SERVICE STUR SERVICE SERV			

LINEAR REFERENCING TABLE




400	100	N 1		ш
116		6 1	шн	-

Г	ROUTE_	D F_MEA	T_MEAS	SIZE	MATEMAL	MATERIAL SUBTYPE	PRESSURE	WR
Г	474	0	14	1"	CWS	√Null>	HP	42-5282-6583-1713
L	474	0 1	71	5/8"	PE	<null></null>	HP	42-5282-6583-1713

	EFV	DATE_INSTALLED	SOURCE	INSERTED	SOAP	PSI	RESEARCH	COMMENT
ì	<null></null>	4/1/1975	1094761	<null></null>	<nul></nul>	150	<null></null>	<nul></nul>
i i	<null></null>	4/1/1975	1094761	YES	<null></null>	150	<null></null>	<nul></nul>
ŝ								

LOCATION CORRECTION



GPSing



- Collecting GPS at riser
 - Through leak survey
 - 3-5 yr program
 - Decision on accuracy
 - Using high-accuracy units
 - Conflate the mapped riser location from historical record on the back end

FINDINGS

- Data from historical cards can be difficult to decipher
- Info was copied from card to card
 - Double checking info was rare
 - Only partial info transferred
- GPS connectivity at riser can be difficult
 - Flood light technology
 - Have procedure when unable to connect

FORWARD

- Coupling mitigation pilot
 - Install new taps for all services from steel main
 - New tap transitions to PE
 - Renew steel services with PE
 - New documentation with better service information
- Future automation
 - Design services in GIS and redline before populating GIS
 - Use GPS coordinates and barcode info to populate GIS



